Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: CLOVER 1-3H

Field Name: MURPHY CREEK Well File #: 18351

Date Incident:3/8/2014Time Incident:07:00Facility ID Number:County:DUNNTwp:145Rna:95Sec:3Qtr:

Location Description: Cultivated field

Submitted By: Patrick Skillestad Received By:

Contact Person: Patrick Skillestad

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	100	Barrels	100	Barrels	100	barrels	
Brine	40	Barrels	40	Barrels	40	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/7/2016 Clean Up Concluded: 3/19/2014

Risk Evaluation:

None

Areal Extent:

Misted oil on snow in cultivated field.

Potential Environmental Impacts:

Topsoil on location and in cultivated field. No impact to water.

Action Taken or Planned:

Standing fluid was sucked up and returned to production tanks. Contaminated snow in culivated field was removed. Contaminated material on location will be removed and disposed of.

Wastes Disposal Location: Chimney Butte Disposal and Knutson Disposal

Agencies Involved:

Updates

Date: 3/9/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, sprayed off location according to the report. Followup is necessary.

Date: 3/11/2014 Status: Inspection Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Contaminated snow has been scraped up and disposed of. Scraped-up soil on pad awaiting disposal. I spoke with a CRI rep on site. He stated that CRI contacted the landowner, and they agreed on the area to be scraped up. CRI pulled soil samples for analysis. Small amount of crude oil still left on piled topsoil to south of pad, but it is being addressed.

Date: 3/10/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.